



**Firmware Version:** 4.2.0.9  
**Published:** May 16,  
2014

**Content:**

Revision History and System Requirement:.....2

New Features: .....2

Problems Fixed: .....4

Known Issues: .....8

Related Documentation:.....12

## Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
Runtime: V4.2.0.9_B009	16-May-14	DWL-6600AP	A1G
Runtime: V4.1.0.14	17-Dec-12	DWL-6600AP	A1G
Runtime: V4.1.0.11	19-Sep-12	DWL-3600AP	A1G
		DWL-6600AP	A1G
		DWL-8600AP	A1G
Runtime: V4.1.0.8	11-Apr-12	DWL-3600AP	A1G
		DWL-6600AP	A1G
		DWL-8600AP	A1G
Runtime: V4.1.0.4	20-Mar-12	DWL-6600AP	A1G
		DWL-8600AP	A1G
Runtime: V4.1.0.2	15-Jan-12	DWL-6600AP	A1G
		DWL-3600AP	A1G

## New Features:

Firmware Version	New Features
V.4.2.0.9_B009	<ul style="list-style-type: none"> <li>Forced roaming support</li> <li>PermaConfig support</li> <li>Ability to disable LEDs using CLI command</li> <li>AP Scheduler</li> </ul>
V4.1.0.14	No new features
V4.1.0.11	<ul style="list-style-type: none"> <li>DWL-6600AP now officially certified for CE DFS (EN 301 893)</li> <li>Throughput has been improved on 3600AP &amp; 6600AP</li> </ul>
V4.1.0.8	CE DFS channels have been restored.
V.4.1.0.4	Disable CE DFS channels for 6600AP
V4.1.0.2	<p>First V4.0 release. Baseline feature reference Ver4.0 functional spec</p> <p>New Features and changes over V3.0.0.16 include</p> <ul style="list-style-type: none"> <li>Aeroscout integration – DWL-3600AP, DWL-6600AP, and DWL-8600AP is now able to work with Aeroscout tags and management software to provide location tracking service.</li> </ul>

- Radio scheduler – The ability for a user to configure windows of time for VAPs or radios to be enabled or disabled
- Rogue AP notification – Syslog messages and traps when new rogue APs are discovered by RF Scan, and email alert will be sent out.
- MIB files have a .mib file extension rather than a .my extension.
- Managed-AP mode is enabled by default
- Dual boot feature no longer supported

## Problems Fixed:

Firmware Version	Problems Fixed
V4.2.0.9_B009	<ol style="list-style-type: none"> <li>1. VoIP phone compatibility issue [<a href="#">HQ20121016000012</a>]</li> <li>2. Low 802.11b throughput [<a href="#">HQ20120912000015</a>]</li> <li>3. Infinite boot loop if NTP server setting is changed to certain countries. [<a href="#">HQ20120914000006</a>]</li> <li>4. AP password and WDS group password are not persisting across configuration restore. [<a href="#">HQ20121008000019</a>]</li> <li>5. Broadcast key refresh failure. [<a href="#">HQ20121119000015</a>]</li> <li>6. Password length is increased to 16 characters. [<a href="#">HQ20130307000027</a>]</li> <li>7. Rogue AP detection is disabled by default. [<a href="#">HQ20130201000009</a>]</li> <li>8. De-authentication frames are sent with the wrong BSSID. [<a href="#">HQ20120809000011</a>]</li> <li>9. AP should push all the configured QOS ACL rules to another in cluster mode. [<a href="#">HQ20120719000008</a>]</li> <li>10. Configuration in Master AP is getting overwritten by the configuration of newly joined AP in cluster. [<a href="#">HQ20130205000001</a>]</li> <li>11. Observed operating channel lock for 5GHz AP when configured for "AU" country code. [<a href="#">HQ20130121000001</a>]</li> <li>12. Manual transmit power setting doesn't work. [<a href="#">HQ20121106000016</a>]</li> <li>13. AP password and WDS group password are not persisting across configuration restore. [<a href="#">HQ20121008000019</a>]</li> <li>14. "t-t" isn't allowed as a SNMP community name. [<a href="#">HQ20130320000004</a>]</li> <li>15. When MAC addresses are different for VLANs in L3 device, then the captive portal redirection will not work. [<a href="#">HQ20130319000013</a>]</li> <li>16. Enable 802.11n for KR, BY, TJ, UA, and UZ country codes [<a href="#">HQ20130401000007</a>], [<a href="#">HQ20130424000015</a>]</li> <li>17. Unable to send email alert when mail server address is configured using domain name. [<a href="#">HQ20130603000008</a>]</li> <li>18. The transmit power of DWL-6600AP is not changing according to settings as sent from a controller device in managed mode. [<a href="#">HQ20130227000007</a>]</li> <li>19. Unable to load image when wireless driver logs is enabled. [<a href="#">HQ20130611000011</a>]</li> <li>20. Some wireless stations cannot access the network after several hours. [<a href="#">HQ20130731000010</a>]</li> <li>21. Special character support. [<a href="#">HQ20130905000009</a>]</li> <li>22. NTP manual setting from GUI is not getting saved in the configuration.</li> </ol>

	<p>[<a href="#">HQ20130913000003</a>]</p> <p>23. AP detection logs are coming with WLAN1 interface only even if the AP is detected on 5GHz channels [<a href="#">HQ20131014000007</a>]</p> <p>24. Unable to configure WPA key with space from GUI. [<a href="#">HQ20131219000020</a>]</p> <p>25. Very low throughput with DWA-125 adapter. [<a href="#">HQ20131106000009</a>]</p> <p>26. Can't receive broadcast packet from wired network to wireless. [<a href="#">HQ20130816000008</a>]</p> <p>27. Multicast enhancement. [<a href="#">HQ20131223000008</a>]</p> <p>28. Low transmit power with 4.2.0.9 FW [<a href="#">HQ20131125000005</a>]</p> <p>29. LAN LED is off after reboot. [<a href="#">HQ20131025000002</a>]</p> <p>30. Making "upgrade twice method" consistent. [<a href="#">HQ20140310000009</a>]</p> <p>31. After a few hours, the AP will lose management and operation on device interfaces will get stuck. Need to update the channel list according to the new regulatory domain configuration. [<a href="#">HQ20130816000008 - Reopen</a>]</p> <p>32. WLAN utilization value get stuck to a certain value. [<a href="#">HQ20131202000015</a>]</p> <p>33. Hostapd process in AP is continuously restarting when only 5GHz radio is enabled. [<a href="#">HQ20140409000013</a>]</p>
V4.1.0.14	<ol style="list-style-type: none"> <li>Optimizes transmit power of the 2.4GHz radio [<a href="#">DGC20120528000001</a>]</li> <li>5GHz radio beacon loss in rare occasions</li> <li>Certain default settings were changed <ul style="list-style-type: none"> <li>Radio scan is disabled by default</li> <li>Optimizing multicast/broadcast behavior to ensure that broadcast traffic won't interfere with unicast</li> </ul> </li> </ol>
V4.1.0.11	<ol style="list-style-type: none"> <li>Intermittent connectivity loss on DWL-3600AP, DWL-6600AP, DWL-8600AP [<a href="#">DGC20120528000001</a>]</li> <li>30 second IAS re-authentication issue [<a href="#">DGC20120315000001</a>]</li> <li>Group key not refreshed correctly, causing broadcast traffic such as DHCP to be lost, and the user may not be able to obtain IP address. [<a href="#">DUSA20120628000002</a>]</li> <li>MIB error [<a href="#">DI201205000002</a>]</li> <li>Clients lose association during Chariot run after ~2 hours [<a href="#">LVL700168082 (Not seen in test of 4.1.0.11. Possibly related to DGC20120528000001. Presume fixed)</a>]</li> </ol>
V4.1.0.8	<ol style="list-style-type: none"> <li>[AP][WDS+SMB] If WDS mode with SMB traffic about 1~2 days, the AP will cause Ethernet port hang [<a href="#">LVL700168205</a>]</li> <li>3600 APs lost management with Undirected ARP Req. floods to the managed switch(4026). [<a href="#">LVL700171117 (config error was the cause)</a>]</li> </ol>

3. AP is not sending UDP 57776 packets when Wireless switch does not have discovery enabled [[LVL700171972](#)]
4. Unable to reliably change WDS encryption without losing DHCP connectivity for extended periods [[LVL700175132](#)]
5. [DWL-8600AP] Unstable signal strength in a secondary BSSID in Multi-SSID [[DI20110218000011-Japan](#)][[LVL700155847](#)]
6. 0xd3d28f8 (wlanWdmTask): Memory Corruption by task id - d3d28f8 and reset [[LVL700163706](#)]
7. failed to load factory defaults seen after firmware upgrade [[LVL700167818](#)]
8. WLAN utilization doesn't change with change in traffic through AP. [[LVL700170915 \(Verified. Function is as designed\)](#)]
9. Locking one radio channel in clustering channel management page causes both radios to be locked. [[LVL700172121 \(test error was the cause\)](#)]
10. Clustered 3600s do not share configs. [[LVL700172122](#)]
11. Mac Authentication black list/white list not operating properly. [[LVL700174532 \(test error was the cause\)](#)]
12. Wireless kept old IP address after changing switch static IP to a new address in same subnet. [[LVL700174733](#)]
13. 6600AP DFS channels do not trigger on RADAR [[LVL700169740](#)]
14. 6600AP crashes while attempting tunneling [[LVL700174549](#)]
15. WDS webpage on 6600AP takes excessively long to load. [[LVL700171955](#)]
16. 3600AP and 6600AP Endurance Test – LAN to Wireless (UDP/ Multicast/ Broadcast), and Wireless to LAN (Multicast/ Broadcast). DUT failed to transmit the traffic to wireless clients after 212 seconds running. [[DBG12020268](#)]
17. The message “invalid image” is displayed in the GUI if the AP was powered off during the boot-up process.
18. not seeing the managed peers on the dlink gui [[LVL700170818 \(Function is as designed. Require peer configuration push\)](#)]

V.4.1.0.4

1. Aeroscout gives error configuring 3600AP. Appears 3600AP fails to respond correctly. [[LVL700174456](#)]
2. [Qos DiffServ Policy] The Committed Rate can't work correctly. [[LVL700168202](#)]
3. AP Crashes if roaming delay test is run for multiple clients using Veriwave [[LVL700170934](#)]
4. 3600 Scheduling not occurring [[LVL700171190](#)]

5. [AP][Client QoS ACL+IPv6] Input ipv6 address ::33, WEB UI will appear debug message. [[LVL700168211](#)]
6. Client database not purged when new cluster controller is elected [[LVL700170909](#)]
7. Scheduler page missing some information. [[LVL700171193](#)]
8. Not able to set the static channel on the ap from the wireless cluster controller [[LVL700171319](#)]
9. Traps being sent to the syslog server do not have the time that was gotten from SNTP. [[LVL700171881](#)]
10. 3600 AP crashed while running Automation suit. [[LVL700174681](#)]
11. 6600AP crashes while sending BCast & MCast flood into managed switch [[LVL700171115](#)]

V.4.1.0.2

Initial release

## Known Issues:

Firmware Version	Issues
4.2.0.9_B009	N/A
V4.1.0.11	<ol style="list-style-type: none"> <li>Setting the time zone in the NTP menu to Poland will cause the AP to go into an infinite reboot cycle. We recommend the user should <b>NOT</b> alter NTP settings until this issue is resolved. [<a href="#">HQ20120914000006</a>]</li> <li>3600 cell recovery - power not adjusting when 1 neighbor goes down [<a href="#">LVL700171102</a>]</li> <li>emWeb hang while pushing peer configuration (can only be repeated with large configuration files in overnight runs). [<a href="#">LVL700174469</a>]</li> <li>[QoS ACL+IPv6] Please remove protocol type: IP and ICMP when IPv6 is selected. [<a href="#">LVL700168204</a>]</li> <li>[AP][Client Qos ACL+IPv6+IGMP] Only permit IPv6:IGMP, but fail. [<a href="#">LVL700168209</a>]</li> <li>Cluster controller pushes power change to RADIUS-power-set AP [<a href="#">LVL700169684</a>]</li> <li>When AP's are assigned addresses with x.x.x.255 they won't communicate to other devices. [<a href="#">LVL700174543 (this is a problem with VxWorks stack. Addresses that ends with 255 is not recommended)</a>]</li> <li>Call recover for a 6600AP – power doesn't go back down after the one neighbor comes back. [<a href="#">LVL700171104</a>]</li> <li>6600AP Web Server-Session Timeout-Test by IE8. The login web page will pop up again and again even user has input correct credentials after the web session timeout. [<a href="#">DBG12020202. Rarely occurs after 4.1.0.8. The workaround is to press Ctrl-F5.</a>]</li> </ol>
V4.1.0.8	<ol style="list-style-type: none"> <li>Clients lose association during Chariot run after ~2 hours [<a href="#">LVL700168082 (difficult to reproduce)</a>]</li> <li>3600 cell recovery - power not adjusting when 1 neighbor goes down [<a href="#">LVL700171102</a>]</li> <li>emWeb hang while pushing peer configuration (can only be repeated with large configuration files in overnight runs). [<a href="#">LVL700174469</a>]</li> <li>[QoS ACL+IPv6] Please remove protocol type: IP and ICMP when IPv6 is selected. [<a href="#">LVL700168204</a>]</li> <li>[AP][Client Qos ACL+IPv6+IGMP] Only permit IPv6:IGMP, but fail. [<a href="#">LVL700168209</a>]</li> </ol>

6. Cluster controller pushes power change to RADIUS-power-set AP [LVL700169684]
7. When AP's are assigned addresses with x.x.x.255 they won't communicate to other devices. [LVL700174543 (this is a problem with VxWorks stack. Addresses that ends with 255 is not recommended)]
8. Call recover for a 6600AP – power doesn't go back down after the one neighbor comes back. [LVL700171104]
9. 6600AP Web Server-Session Timeout-Test by IE8. The login web page will pop up again and again even user has input correct credentials after the web session timeout. [DBG12020202]

V4.1.0.4

1. Clients lose association during Chariot run after ~2 hours [LVL700168082]
2. [AP][WDS+SMB] If WDS mode with SMB traffic about 1~2 days, the AP will cause Ethernet port hang [LVL700168205]
3. 3600 cell recovery - power not adjusting when 1 neighbor goes down [LVL700171102]
4. 3600 APs lost management with Undirected ARP Req. floods to the managed switch(4026).[LVL700171117]
5. AP is not sending UDP 57776 packets when Wireless switch does not have discovery enabled [LVL700171972]
6. emWeb hang while pushing peer configuration (can only be repeated with large configuration files in overnight runs).[LVL700174469]
7. Unable to reliably change WDS encryption without losing DHCP connectivity for extended periods [LVL700175132]
8. [DWL-8600AP] Unstable signal strength in a secondary BSSID in Multi-SSID [DI20110218000011-Japan][LVL700155847 (rejected)]
9. 0xd3d28f8 (wlanWdmTask): Memory Corruption by task id - d3d28f8 and reset [LVL700163706]
10. failed to load factory defaults seen after firmware upgrade [LVL700167818]
11. [QoS ACL+IPv6] Please remove protocol type: IP and ICMP when IPv6 is selected. [LVL700168204]
12. [AP][Client Qos ACL+IPv6+IGMP] Only permit IPv6:IGMP, but fail. [LVL700168209]
13. Cluster controller pushes power change to RADIUS-power-set AP [LVL700169684]
14. not seeing the managed peers on the dlink gui [LVL700170818]

15. WLAN utilization doesn't change with change in traffic through AP. [LVL700170915]
16. Locking one radio channel in clustering channel management page causes both radios to be locked. [LVL700172121]
17. Clustered 3600s do not share configs. [LVL700172122]
18. Mac Authentication black list/white list not operating properly. [LVL700174532]
19. When AP's are assigned addresses with x.x.x.255 they won't communicate to other devices. [LVL700174543]
20. Wireless kept old IP address after changing switch static IP to a new address in same subnet. [LVL700174733]
21. 6600AP DFS channels do not trigger on RADAR [LVL700169740]
22. 6600AP crashes while attempting tunneling [LVL700174549]
23. Call recover for a 6600AP – power doesn't go back down after the one neighbor comes back. [LVL700171104]
24. WDS webpage on 6600AP takes excessively long to load. [LVL700171955]
25. 3600AP and 6600AP Endurance Test – LAN to Wireless (UDP/ Multicast/ Broadcast), and Wireless to LAN (Multicast/ Broadcast). DUT failed to transmit the traffic to wireless clients after 212 seconds running. [DBG12020268]
26. 6600AP Web Server-Session Timeout-Test by IE8. The login web page will pop up again and again even user has input correct credentials after the web session timeout. [DBG12020202]

V4.1.0.2

1. Aeroscout gives error configuring 3600AP. Appears 3600AP fails to respond correctly. [LVL700174456]
2. Clients lose association during Chariot run after ~2 hours [LVL700168082]
3. [Qos DiffServ Policy] The Committed Rate can't work correctly.[LVL700168202]
4. [AP][WDS+SMB] If WDS mode with SMB traffic about 1~2 days, the AP will cause Ethernet port hang [LVL700168205]
5. AP Crashes if roaming delay test is run for multiple clients using Veriwave [LVL700170934]
6. 3600 cell recovery - power not adjusting when 1 neighbor goes down [LVL700171102]
7. 3600 APs lost management with Undirected ARP Req. floods to the managed switch(4026).[LVL700171117]

8. 3600 Scheduling not occurring [[LVL700171190](#)]
9. AP is not sending UDP 57776 packets when Wireless switch does not have discovery enabled [[LVL700171972](#)]
10. emWeb hang while pushing peer configuration [[LVL700174469](#)]
11. Unable to reliably change WDS encryption without losing DHCP connectivity for extended periods [[LVL700175132](#)]
12. [DWL-8600AP] Unstable signal strength in a secondary BSSID in Multi-SSID [[DI20110218000011-Japan](#)][[LVL700155847](#)]
13. 0xd3d28f8 (wlanWdmTask): Memory Corruption by task id - d3d28f8 and reset [[LVL700163706](#)]
14. failed to load factory defaults seen after firmware upgrade [[LVL700167818](#)]
15. [QoS ACL+IPv6] Please remove protocol type: IP and ICMP when IPv6 is selected. [[LVL700168204](#)]
16. [AP][Client QoS ACL+IPv6+IGMP] Only permit IPv6:IGMP, but fail. [[LVL700168209](#)]
17. [AP][Client QoS ACL+IPv6] Input ipv6 address ::33, WEB UI will appear debug message. [[LVL700168211](#)]
18. Cluster controller pushes power change to RADIUS-power-set AP [[LVL700169684](#)]
19. not seeing the managed peers on the dlink gui [[LVL700170818](#)]
20. Client database not purged when new cluster controller is elected [[LVL700170909](#)]
21. WLAN utilization doesn't change with change in traffic through AP. [[LVL700170915](#)]
22. Scheduler page missing some information. [[LVL700171193](#)]
23. Not able to set the static channel on the ap from the wireless cluster controller [[LVL700171319](#)]
24. Traps being sent to the syslog server do not have the time that was gotten from SNTP. [[LVL700171881](#)]
25. Locking one radio channel in clustering channel management page causes both radios to be locked. [[LVL700172121](#)]
26. Clustered 3600s do not share configs. [[LVL700172122](#)]
27. Mac Authentication black list/white list not operating properly. [[LVL700174532](#)]
28. When AP's are assigned addresses with x.x.x.255 they won't communicate to other devices. [[LVL700174543](#)]
29. 3600 AP crashed while running Automation suit. [[LVL700174681](#)]

30. Wireless kept old IP address after changing switch static IP to a new address in same subnet. [[LVL700174733](#)]
31. 6600AP DFS channels do not trigger on RADAR [[LVL700169740](#)]
32. 6600AP crashes while sending BCast & MCast flood into managed switch [[LVL700171115](#)]
33. 6600AP crashes while attempting tunneling [[LVL700174549](#)]
34. Call recover for a 6600AP – power doesn't go back down after the one neighbor comes back. [[LVL700171104](#)]
35. WDS webpage on 6600AP takes excessively long to load. [[LVL700171955](#)]

### **Related Documentation:**

---

- DWS-x600AP Series Manual
- DWS-x600AP Series CLI Manual