



Firmware Version: 1.01rc01

Published Date: 2013/05/08

Content:

Upgrading Instructions:	2
Upgrading by using Web-UI	2
New Features:	2
Changes of MIB & D-View Module:	2
Problems Fixed:	2
Known Issues:	3
Related Documentation:	3





Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
1.01rc01	2013/05/08	DAP-3310	A1

Upgrading Instructions:

D-Link AP supports firmware upgrading via Web-UI. You may download the firmware from D-Link web site http://tsd.dlink.com.tw.

Upgrading by using Web-UI

- 1. Connect a work station to the LAN port of Access Point.
- 2. Open the web browser of work station and entering the IP address of the AP. The system default IP address is 192.168.0.50.
- 3. Enter administrator's username and password, user name is "admin" and leave the password field blank by default.
 - To update the AP's firmware, click **Maintenance > Firmware and SSL Certification Upload**



New Features:

First Release

Changes of MIB & D-View Module:

None

Problems Fixed:

Firmware Version	Problems Fixed		
	1. Fix WEP encryption cannot work on WDS with AP mode.		
	2. Fix wireless can't be turned off when wireless security is		
V1.01rc01	WPA/WPA2-Personal/Enterprise or 802.1x.		
	3. Fix WPA/WPA2-Enterprise with EAP can work issue in client mode.		
	4. Fix wireless can't work when Time Policy enabled and no rule		





DAP-3310 Firmware Release Notes

5. V

Known Issues:

Firmware Version	Known Issues
V1.01rc01	None

Related Documentation:

None

