



Firmware Version: 1.00rc011

Published Date: 2015/Aug/13

Content:

Upgrading Instructions:..... 2
 Upgrading by using Web-UI..... 2
New Features:..... 2
Changes of MIB & D-View Module:..... 2
Problems Fixed: 2
Known Issues: 3
Related Documentation: 3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
1.00rc011	2015/Aug/13	DAP-3320	A1


Upgrading Instructions:

D-Link AP supports firmware upgrading via Web-UI. You may download the firmware from D-Link web site <http://tsd.dlink.com.tw>.

Upgrading by using Web-UI

1. Connect a work station to the LAN port of Access Point.
2. Open the web browser of work station and entering the IP address of the AP. The system default IP address is 192.168.0.50.
3. Enter administrator's username and password, user name is "admin" and leave the password field blank by default.

To update the AP's firmware, click **Maintenance > Firmware and SSL Certification Upload**



New Features:

1. Firmware first release
2. AP Array tool first release
3. CWM module first release (CWM platform v1.02)

Changes of MIB & D-View Module:

None

Problems Fixed:

Firmware Version	Problems Fixed
------------------	----------------

V1.00rc011	None
------------	------

Known Issues:

Firmware Version	Known Issues
V1.00rc011	None

Related Documentation:

None