

DWA-171 Wireless AC Dual-Band Nano USB Adapter

Version: 1.06b01 Hardware: A1

Date: 2015/Oct/13

Driver:

Windows XP x86 –1026.13.0.0625.2014 (WHQL pass)
Windows XP x64 –1026.13.0.0625.2014 (WHQL pass)
Windows Vista x86 –1026.13.0.0625.2014 (WHQL pass)
Windows Vista x64 –1026.13.0.0625.2014 (WHQL pass)
Windows 7 x86 –1026.13.0.0625.2014 (WHQL pass)
Windows 7 x64 –1026.13.0.0625.2014 (WHQL pass)
Windows 8 x86 –1026.13.0.0625.2014 (WHQL pass)
Windows 8 x64 –1026.13.0.0625.2014 (WHQL pass)
Windows 8 x64 –1026.13.0.0625.2014 (WHQL pass)
Windows 8.1 x86 –1026.13.0.0625.2014 (WHQL pass)
Windows 8.1 x64 –1026.13.0.0625.2014 (WHQL pass)
Windows 10 x86 –1030.0.0515.2015 (WHQL pass)
Windows 10 x64 –1030.0.0515.2015 (WHQL pass)


Problems Resolved:

NA

Enhancement:

- 1. Support Windows10 x86 and x64
- 2. Improve driver installation procedure: Double click "Setup.exe" and user can select

"Upgrade" to replace existing driver or select "Remove" to remove the drivers from computer.





Known Issue:

In Windwos10, WPA/WPA2-EAP connection fails when using D-Link connection manager. User can disable D-Link connection manager and using Windows built-in auto-configuration tool to connect with WPA/WPA2-EAP AP/Router.