



Firmware Version: V4.3.0.2_B045
Published: Sept 03, 2015

Content:

Revision History and System Requirement:.....2

New Features:2

Problems Fixed:2

Known Issues:3

Related Documentation:.....3

Revision History and System Requirement:

FW Version	Date	Model	HW	MD5 CHECKSUM
V4.3.0.2_B045	03-Sept-2015	DWL-6610AP	A1	a5537d79abccec596621b793f2b5a977

New Features:

Firmware Version	New Features
V4.3.0.2_B045	N/A
	1. Initial release
V4.3.0.2_B042	2. Root Access should be denied for admin CLI user to counter moose vulnerability

Problems Fixed:

Firmware Version	Problems Fixed
V4.3.0.2_B045	<p>47828 P1 DBG15070062 AP is getting reboot continuously when user tries to configure in channel management page in cluster setup.</p> <p>52326 P1 DBG15070086 DLab_DWL-8610_AP hang while using Wireshark capturing the packet</p> <p>52666 P1 DBG15070065 Weird symbols are seen in authentication page</p> <p>52663 P1 HQ20150702000013 Australia Country Code should support DFS channels in DWL-APs</p> <p>52212 P1 HQ20150625000003 The AP does not accept admin login password that contains special characters.</p> <p>52548 P1 HQ20150617000002 Clients drop their connection and cannot connect back until restart.[DUSA20150610000002-Canada]</p>
V4.3.0.2_B042	<ol style="list-style-type: none"> Power LED is not working in DWL-6610AP Hard Reset button is not working LAN and RF LED are not blinking with network traffic. RF LED will be off, if 2nd SSID(VAP) is enabled. HQ20150421000003 MAC Authentication using Radius is not working based on Radius Server response. HQ20150602000012 Radius settings are overwritten to 10.90.90.1/NOPASSWORD after AP is managed by DWC-2000 HQ20150529000008 Two radio show transmit power to 0 in the packets



Known Issues:

Firmware Version	Issues

Related Documentation:

- DWS-x600AP Series Manual
- DWS-x600AP Series CLI Manual