



Firmware Version: V4.6.2.2 Published: July 15, 2020

Copyright Notice

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

Disclaimer

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

Limitations of Liability

UNDER NO CIRCUMSTANCES SHALL D-LINK OR ITS SUPPLIERS BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE D-LINK PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF D-LINK IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, D-LINK WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. D-LINK WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT D-LINK RECEIVED FROM THE END-USER FOR THE PRODUCT.

Content:

Revision History and System Requirement:	2
New Features:	2
Problems Fixed:	2
(nown Issues:	3
Related Documentation:	3





Revision History and System Requirement:

FW Version	Date	Model	HW	MD5 CHECKSUM
V4.6.2.2	15-July-2020	DWL-6610AP DWL-6610APE	B1	a0b4a5faccc95b4f9b1dd19dd0aacce7

Important Note:

1. The firmware for DWL-6610AP/B1 is not compatible with DWL-6610AP/A1 hardware. Please **DO NOT** try to install this firmware to DWL-6610AP/A1.

New Features:

Firmware Version	New Features
V4.6.2.2	N/A

Problems Fixed:

Firmware Version	Problems Fixed
	1. Fix Issue ID 0057265 (HQ20180706000008): Station has no network after
	associated
	2. Fix Issue ID 0057189 (HQ20180703000008): Gateway disappear after managed
	3. Fix Issue ID 0057166 (HQ20180704000013): Set SSID security as
V4.6.2.2	WPA-Enterprise but client device detects as WPA-Personal
V4.0.2.2	4. Fix Issue ID 0063350: DKP1810013-0129-[HQ20170413000010]
	D-Track_2017_04_Time Setting Issue (VBG19100520)
	5. Fix Issue ID 0063351: DKP1810013-0099 radio interface list issue when test
	Packet Capture Remote capture mode (VBG19100609)
	6. Fix v4.6.2.1 UDP throughput issue (DBG20050139)
	1. Fix WPA2 KRACK vulnerability.
	2. Fix the displayed model name on the web GUI of DWL-6610APE.
V4.C0.F	3. Fix sometimes unusual disconnection when enabling Automatic RF power on
V4.6.0.5	management mode. [DI20171212000006]
	4. Fix disabling WPA would make DWL-6610AP can't be managed
	[DEUR20171222000001, DEUR20171212000005]





5. Fix throughput drop after AP rebooted.
6. Fix multicast packets flooding from other VLAN. [DEUR20180206000006]
7. Fix DWC-2000 does not properly show 802.11ac clients which connect to
DWL-6610B1 AP. [DEUR20180131000003]
8. Fix multicast streaming freeze issue.
9. Fix start up channel in Auto mode become the same mostly.
10. Fix DWL-6610AP B1 could become Rogue AP in Discover AP List page after
managed.

Known Issues:

Firmware Version	Issues
	1. Beacon does not contain WMM/WME parameter element [DBG20050176]
	2. CP login page is not triggered properly with DWL-3610AP and DWL-6610AP/B1
V4.6.2.2	[DEUR20200507000004/ HQ20200514000006]
	3. DBG20070773 5G client will link to 11a mode after management by
	DWC-1000/C1/v4742 use default profile. (but specific HW profile OK)

Related Documentation:

- DWL-X600AP_X610AP_6700AP_8710AP_X620AP Unified_AP_V6.61(WW) DWL-x600AP_CLI Guide_v2.0

