



Firmware Version: 1.01r013

Published Date: 2025/09/11

Content:

Upgrading Instructions:	. 2
Upgrading by using Web-UI	. 2
New Features:	. 3
Changes of MIB & D-View Module:	. 3
Problems Fixed:	. 3
Known Issues:	. 3
Related Documentation:	. 3





Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
1.00r005	2024/08/27	DAP-X3060OU	A1

Upgrading Instructions:

D-Link AP supports firmware upgrading via Web-UI. You may download the firmware from D-Link web site http://tsd.dlink.com.tw.

Please also

- 1. Make sure your DAP-X30600U has to manually assign a valid static IPv4 address or get a valid IPv4 address from DHCP server before upgrade FW.
- 2. Do not power off your DAP-X3060OU when FW upgrading.

Upgrading by using Web-UI

- 1. Connect a work station to the LAN port of Access Point.
- 2. Open the web browser of work station and entering the IP address of the AP. The system default IP address setting is dynamic ip, and you can enter http://dapx3060OU.local to login, if it cannot get ip address from DHCP server, it's ip address will back to 192.168.0.50.
- 3. Enter administrator's username and password, user name and password are "admin" by default
 - To update the AP's firmware, click **Maintenance > Firmware and SSL Certification Upload**





New Features:

- 1. Enable all DFS channels, and then provide an option to enable or disable the weather channel.
- 2. Captive Portal enhancements: External Captive Portal/MAC address authentication/ Walled Garden
- 3. Support Auto RF Optimization with DNC
- 4. VueJS V3.0 replace Angular JS for Web pages

Changes of MIB & D-View Module:

None

Problems Fixed:

Firmware Version	Problems Fixed		
	Modify the power table CTL setting for IC/AU certification in the hardware.		
	2. Modified power table for India (IN domain).		
	3. Vietnam Country (VN domain): 2.4G power limited to 17 dBm.		
V1.01	4. 5GHz Channel Width default changes to Auto 20/40 MHz.		
	5. Fixed [DI20250221000002-Japan] : ACL Table Upload fails, fixed VAP layout for subCfgIDMacACL		
	6. Fixed [DI20241015000002-Japan] : Doesn't initialize ssh resources properly after changing Timeout		

Known Issues:

Firmware Version	Known Issues		
V1.01	None		

Related Documentation:

DAP-X3060OU user manual v1.00

