

## **DWA-182 AC1200 Dual Band USB Adapter**

Version: 3.05b01 Hardware: A1

Date: 2015/Oct/21

Driver:

Windows XP x86 –1027.6.0417.2015 (WHQL pass)
Windows XP x64 –1027.6.0417.2015 (WHQL pass)
Windows Vista x86 –1027.6.0417.2015 (WHQL pass)
Windows Vista x64 –1027.6.0417.2015 (WHQL pass)
Windows 7 x86 –1027.6.0417.2015 (WHQL pass)
Windows 7 x64 –1027.6.0417.2015 (WHQL pass)
Windows 8 x86 –1027.6.0417.2015 (WHQL pass)
Windows 8 x64 –1027.6.0417.2015 (WHQL pass)
Windows 8.1 x86 –1027.6.0417.2015 (WHQL pass)
Windows 8.1 x64 –1027.6.0417.2015 (WHQL pass)
Windows 10 x86 –1030.0.0515.2015 (WHQL pass)
Windows 10 x64 –1030.0.0515.2015 (WHQL pass)

## **Problems Resolved:**

1. Fixed WPS issue: unable to connect AP/Router by WPS after un-plug and plug-in dongle.

## **Enhancement:**

- 1. Support Windows10 (x86 and x64)
- Improve driver installation procedure: Double click "Setup.exe" and user can select
   "Upgrade" to replace existing driver or select "Remove" to remove the drivers from computer.





## **Known Issue:**

In Windows10, if user frequently switch SSID between 2.4GHz and 5GHz, the transmit speed will limited to USB2.0 standard.