DHP-W306AV/DHP-W307AV Firmware Release Notes

Firmware: 1.01WW to 1.03BQ

Hardware: A2

Date: 2011/06/15

Problems Resolved:

None

Enhancements:

Change pre-scale setting

Delay 300 seconds to make DUT entering power saving mode

Known Issues:

None