DVG-5004S Firmware Release Notes

Firmware: 1.2.38.99.228.k195

Hardware: D1

Date: 2017/03/10

Enhancements:

Bug Fixed:

1. WAN2 routing issue fixed. < HQ20170308000001>

Known Issues:

None

Firmware: 1.2.38.96_1.4.2.252.712

Hardware: D1

Date: 2016/04/19

Enhancements:

Bug Fixed:

2. Wan 2 interface cannot to send valn tag packet to PPP server. <DBG16030124>
3. 2ports (80,5060) of DUT are opened by nmap scan from WAN.< DBG16030130>

Known Issues:

None

Firmware: 1.2.38.96_1.4.2.252.680
Hardware: D1
Date: 2016/02/22

Enhancements:

First release.

Bug Fixed:

None

Known Issues:

None