![D-Link - Building Networks for People]

DWA-182 Firmware Release Note

Firmware: v3.02b05

Hardware: C1

Date: 18, Mar, 2014

XP/XP64:   **1024.9.1219.2013**

Vista/Vista-64:   **1024.9.1219.2013**

Win7/Win7-64:   **1024.9.1219.2013**

Win8/Win8-64:   **1024.9.1219.2013**

Win8.1/Win8-64:   **1026.4.1023.2013**

Problems Resolved:

Fix Wizard incorrect page information.

(1) When changing USB mode, the connection will be re-connected.

(2) When changing USB mode, the utility will disappear during 10s-15s.

(3) XP/XP64 do not support utility, so users can't use the utility to create the WPS connection.

(4) Win8 remove hardware icon might be disappear.

(5) When the security is Shared key, the configuration of Utility profile is not accordant.

Enhancements:

1.   NA