



DAP-1350 Firmware Release Note

Firmware: v1.14 (WW)

Hardware: A1

Date: 29, May, 2012

Problems Resolved:

1. Fix TSD0010382 and TSD0011014: Disable WPS-PIN Method issue.
2. Fix firmware upgrade issue when AP mode switches to Router mode.

Enhancements:

1. N/A
-