



Firmware Version: V4.4.0.6
Published: June 4, 2015

Content:

Revision History and System Requirement:.....2

Important Notes:2

New Features:2

Problems Fixed:2

Known Issues:3

Related Documentation:.....3

Revision History and System Requirement:

Firmware Version	Date	Model	HW Version	MD5 Checksum
V4.4.0.6	04-June-2015	DWL-6700AP	A1/A2	43d0158d8ab6e3edfa2a6a1eeefd2c28
V4.4.0.1_B007	02-Feb-2015	DWL-6700AP	A1	142e74f6573015769c8bd609dff6d83
V4.4.0.1_B003	02-Dec-2014	DWL-6700AP	A1	52bd97b7f11249acc50b6e16c7b84339
V4.4.0.1_B001	22-Oct-2014	DWL-6700AP	A1	fc86bb29aa0072406b9afc0dc48d0e82

Important Notes:

1. Setting 5GHz WDS, the 5GHz SSID doesn't serve WLAN client in WDS mode.

New Features:

Firmware Version	New Features
V4.4.0.6	<ol style="list-style-type: none"> 1. Rename V4.4.0.1_B007 to V4.4.0.6 2. OpenSSL Issue, V4.4.0.6 is using 0.9.8ze and it doesn't have the security vulnerabilities.
V4.4.0.1_B007	N/A
V4.4.0.1_B003	N/A
V4.4.0.1_B001	Initial release

Problems Fixed:

Firmware Version	Problems Fixed
V4.4.0.6	N/A
V4.4.0.1_B007	<ol style="list-style-type: none"> 1. Wireless Settings - Transmit Power Fail (DBG14120573) 2. Wireless Settings - Multicast Forwarding Fail (DBG14120574) 3. Log message issue (DBG14120576) 4. WiFi Interface Number, Wifi MAC rule not follow 6600 (2.4G and 5G should switch) (DBG14120578) 5. Basic Settings - Password will change to empty after change System Settings (DBG14120581)

V4.4.0.1_B003	<ol style="list-style-type: none"> 1. The status of Scheduler Profile is not consistency after the AP rebooted. (DBG14110008) 2. LED function did not work (DBG14110005) 3. Unable to configure RADIUS IP Address (DBG14110006)
V4.4.0.1_B001	Initial release

Known Issues:

Firmware Version	Issues
V4.4.0.6	<ol style="list-style-type: none"> 1. The following software features are not ready yet. <ul style="list-style-type: none"> RF Scheduler Forced Roaming Perma Config Hidden page Facebook Wi-Fi Payment Gateway 2. OpenSSL Issue, V4.4.0.6 is using 0.9.8ze and it doesn't have the security vulnerabilities.
V4.4.0.1_B007	<ol style="list-style-type: none"> 1. The following software features are not ready yet. <ul style="list-style-type: none"> RF Scheduler Forced Roaming Perma Config Hidden page Facebook Wi-Fi Payment Gateway

Related Documentation:

- DWL-x600AP Series Manual