



DAP-1522 Firmware Release Note

Firmware: v2.01 (build b02)

Hardware: B1

Date: 04, Jul, 2011

Problems Resolved:

1. Guest Zone disable by default, and user can't access AP.

Enhancements:

1. DFS enabled (ETSI EN301893 V1.5.1)
 2. Support US Canada, EU, AU, China, Israel, Latin America and Taiwan domain code.
-