



DAP-1533 Firmware Release Note

Firmware: v1.02

Hardware: A1

Date: 15, Mar, 2012

Problems Resolved:

1. Fixed TSD Bug ID 0006882 : WPA/WPA2 Encryption Configuration Test – Bridge Mode.
2. Fixed TSD Bug ID 0006960 : Site Survey and Join Network Test - DUT Fail to join special character - Bridge Mode.
3. Fixed TSD Bug ID 0007436 : WEP Encryption Configuration Test - Bridge Mode
4. Fixed TSD Bug ID 0010228 : Web UI Check - All Modes
5. Fixed TSD Bug ID 0010229 : Channel Configuration Test-Domain - 5G AP Mode
6. Fixed TSD Bug ID 0010230 : Web UI Check - All Modes
7. Fixed TSD Bug ID 0010575 : WPS Configuration Test - Overwrite WPS Settings Test - 2.4G & 5G AP Modes
8. Fixed TSD Bug ID 0010591(Step 1) : Setup Wizard Test - Procedure - 2.4G & 5G Mode.
9. Fixed TSD Bug ID 0010608 : Site Survey and Join Network Test - Scan Table - Bridge Mode
10. Fixed TSD Bug ID 0010897 : Setup Wizard Test - WEP - Bridge Mode
11. Fixed TSD Bug ID 0010908(Step 1&2) : Setup Wizard Test - Procedure - Bridge Mode
12. Fixed TSD Bug ID 0010926 : Setup Wizard Test - Security - Bridge Mode
13. Fixed TSD Bug ID 0010955 : Setup Wizard Test - SSID Configuration - 2.4G & 5G AP Mode
14. Fixed TSD Bug ID 0011169 : AP Mode Advance Test - MAC Address Filter - 2.4G & 5G AP Modes.
15. Fixed TSD Bug ID 0006986 : Help Check - Bridge Mode.

Enhancements:

1. New UI spec implement
-