



## DAP-1620 Firmware Release Notes

**Firmware: FW v1.05**

**Hardware: Rev. Ax**

**Data:2017/02/15**

### **Problem Resolved:**

- Keep LED blink until uplink connected to router after finish WPS.
- Fix EDGE browser compatibility issue.

----- END -----