



**Firmware Version:** 1.03rc018

**Published Date:** 2016/03/24

---

### Content:

Upgrading Instructions:.....	2
Upgrading by using Web-UI.....	2
New Features:.....	2
Changes of MIB & D-View Module:.....	2
Problems Fixed: .....	3
Known Issues: .....	3
Related Documentation: .....	3

## Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
1.03rc015	2016/03/24	DAP-2230	A1


## Upgrading Instructions:

D-Link AP supports firmware upgrading via Web-UI. You may download the firmware from D-Link web site <http://tsd.dlink.com.tw>.

### Upgrading by using Web-UI

1. Connect a work station to the LAN port of Access Point.
2. Open the web browser of work station and entering the IP address of the AP. The system default IP address is 192.168.0.50.
3. Enter administrator's username and password, user name is "admin" and leave the password field blank by default.

To update the AP's firmware, click **Maintenance > Firmware and SSL Certification Upload**



## New Features:

None

## Changes of MIB & D-View Module:

None

**Problems Fixed:**

---

<b>Firmware Version</b>	<b>Problems Fixed</b>
V1.03	1. Fixed security issue of web server is vulnerable to buffer overflow while parsing the cookie.

**Known Issues:**

---

<b>Firmware Version</b>	<b>Known Issues</b>
V1.03	None

**Related Documentation:**

---

None