



Firmware Version: V4.2.0.1
Published: Sep 24, 2012

Content:

Revision History and System Requirement:.....2

New Features:2

Problems Fixed:2

Known Issues:2

Related Documentation:.....2

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
Runtime: V4.2.0.1	24-Sep-2012	DWL-2600AP	A1

New Features:

Firmware Version	New Features
V4.2.0.1	Initial release

Problems Fixed:

Firmware Version	Problems Fixed
V4.2.0.1	1. Setting the time zone in the NTP menu to Poland will cause the AP to go into an infinite reboot cycle. [HQ20120914000006]

Known Issues:

Firmware Version	Issues
V4.2.0.1	Initial release

Related Documentation:

- DWS-x600AP Series Manual
- DWS-x600AP Series CLI Manual