

DAP-1513 Firmware Release Note

Firmware: v1.02 Hardware: A1

Date: 07, Jun, 2012

Problems Resolved:

- 1. Fixed the bug of WMM priority tags which did not set from ether port (QOS)(driver modified).
- 2. Fixed the bug that HW WPS button still work after uncheck WSP from Web UI.

Enhancements:

NA