



DAP-1522 Firmware Release Note

Firmware: v2.01 (build b06)

Hardware: B1

Date: 30, Aug, 2011

Problems Resolved:

1. DFS patch for channel selection after radar detection

Enhancements:

1. NA
-