



DWA-140 D1 RangeBooster N USB Adapter Firmware Release

Notes

Firmware: UI 2.6.4.0

Hardware: D1

Date: 2014/08/06

Driver: 4.2.9.4

System Requirement:

Mac OS X v10.6, 10.7, 10.8, 10.9

Software Supported:

For Mac OS X 10.9.X:

D-Link Utility-Install.pkg

For Mac OS X 10.8.X:

D-Link Utility-Install.pkg

For Mac OS X 10.7.X:

D-Link Utility-Install.pkg

For Mac OS X 10.6.X:

D-Link Utility-Install.pkg

Problems Resolved:

Support Mac OS 10.9.

Known issue:

NA
